QUALITY CONTROL

Name of the Work:	Improvements to drains at Maheshwarinagara and Kempegowdanagara 6th B cross R/S Ward.No. 15
Job No:	015-13-000037
Work order No:	132/04.09.2013
BR No:	460/31.10.2013

On verification of quality control test reports available in the file and also from inspection report of Technical Team Deployed for this purpose generally the work executed is satisfactory. Compliance of Quality Control Test Reports as per MORT&H at this stage is not feasible since this work was executed Two years back.

Assistant Executive Engineer
Dasarahalli Sub Division
Bruhat Bengaluru Mahanagara Palike

31/9/15

Executive Engineer
Dasarahalli Division, Dasarahalli Zone
Bruhat Bengaluru Mahanagara Palike